EE 3340 Homework Problem #010

Use the phasor analysis method to solve for the AC steady-state mesh currents, and then express each as a function of time with the phase angles in degrees.

