## EE 3340 Homework Problem #001

Several complex numbers are given in various forms below. Complete the table by filling in the missing entries. *All angles should be in degrees*.

Rectangular Form	Polar Form	Exponential Form
2+ <i>j</i> 2	2√2∠45°	$2\sqrt{2}e^{j45^\circ}$
	3∠0°	
1-j		
		$2\sqrt{2}e^{-j45^\circ}$